



#### GIVI MISURE s.r.l.

Via Assunta 57 - 20054 NOVA MILANESE (MI) ITALY TEL.+39 0362.36.61.26 FAX +39 0362.36.68.76 www.givimisure.it sales@givimisure.it

Code	Project	Release	Title
ST28	A25-B	В	SAFETY DATASHEET

### **ACCESSORIES**





### Aluminium support

To be fixed on the machine to support the magnetic band

#### **ATTENTION!**

It is NOT possible to use the support SP202 if the magnetic band MP200Z is already covered by CV103.

# **ORDERING CODE OF ACCESSORIES**

MODEL	LENGTH (mm)
CV103	XXXXX
SP202	xxxxx

## **INSTALLATION AND HANDLING**

- 1. Degrease the surface where you want to place the magnetic band by using alcohol and dry it carefully.
- 2. Place the band and keep it aligned with the reader head ensuring that the magnetic part is just next to the sensor.
- 3. Place the cover CV103 or the support SP202, if provided.
- 4. The max. adhesion will be achieved after 48 hours from sticking.
- 5. Keep other magnetic parts clear from the tape.
- 6. Store and roll up the tape keeping the magnetic strip on the outside, in order to avoid tensions.

introduce as

GQ067\_P02 (B) ST P